

# TA-Series NTP Network Time Server

## Firmware Version Control

Models Covered: TA110, TA210, TA310, TA610  
Document Number: T1321-03  
Date: 23 Feb 2026

The latest version of this user guide can be obtained from [TimeToolsLtd.com](http://TimeToolsLtd.com)

To take advantage of new features, security updates and bug fixes, TimeTools recommends that customers regularly check that their TA-Series network time servers firmware is up to date.

Firmware updates can be downloaded from TimeTools website at:

<https://timetoolsltd.com/support/download/ta-series-firmware/>

### **Firmware Release: 1.01**

Initial create. Pre-production.

### **Firmware Release: 1.02**

Initial production release.

### **Firmware Release: 1.03** **Release Date: 23-FEB-26**

Updated third party software packages:

SSH 10.2p1 Various bug fixes.

SSL 3.5.5 Switch to OpenSSL 3.5 LTS  
Various bug fixes.  
CVE-2025-11187, CVE-2025-15467, CVE-2025-15468, CVE-2025-15469,  
CVE-2025-66199, CVE-2025-68160, CVE-2025-69418, CVE-2025-69419,  
CVE-2025-69420, CVE-2025-69421, CVE-2026-22795, CVE-2026-22796,  
CVE-2025-9230, CVE-2025-9231, CVE-2025-9232.

nginx 1.28.2 Various bug fixes.  
CVE-2026-1642, CVE-2025-53859, CVE-2025-23419, CVE-2024-7347,  
CVE-2024-32760, CVE-2024-31079, CVE-2024-35200, CVE-2024-34161.

net-snmp 5.9.5.2 Various bug fixes,  
CVE-2025-68615.

*While reasonable efforts have been taken in the preparation of this document to ensure its accuracy, TimeTools Limited assumes no liability resulting from any errors or omissions in this manual, or from the use of the information contained herein.*